

SOUTH PRODUCTION NOTES

April 4, 2015
Mids/day Shift Notes

BASF EMPLOYEES

68 Last Recordable
644 Last Lost Time

108 Days To RC Audit

Be sure to check weigh all bags off of the calciners and fill out the log sheet downstairs by the scale and attach "Packaged By" label with your initials.

#1 MED / AI 5637:

High priority to keep line running through weekend. Need to get to batch 424ish. Add the wet mix on 2nd floor (1/2 drums per batch). Use the good powder from each drum, and discard the hard, rocky, solidified material to Haz waste drum. Please note that Bodmann updated the total solution for each batch (see MOD). May need to periodically change out the blower filter – inspect and change as necessary.

#1 RC / AI 5637:

Calciner is running now. Mill screen changed out Friday afternoon.
Exhaust to Trimer

#2 MED line / Cu 0860:

Down until we can get the calciner syntron fixed.
When running, add ¼ drum wet mix to each batch or use the cart.
NOTE: there are a number of drums on the 2nd deck mezzanine...these can be sealed up, weighed, and be put in the red area to be sent out as copper reclaim. Monitor transition sock for leakage. New transition socks are being looked into. Only one grab sample is needed/shift. Any questions, contact Justin.

#2 RC/ Cu 0860:

Down until the syntron can be evaluated by maintenance.
Lab has been contacted to look at our SA machines.
PLEASE monitor and check surface areas, and contact Justin Quach if out of range for specific corrective instructions. Continue to feed in batch order. Do not feed the bag marked lot 719/720.
F1 overflowed again today

Currently exhausting to CTO (F1 has reservoir overflow issues).

#3 Cleaning:

Need to finish the dryer cleanup on this high priority clean up. The dryer and spiral are what needs completed.

NOTE: The #3 viron packing was scheduled to be replaced on the week of the 30th.

#3 RC / Ni 2458:

Running now.

Need to monitor and make sure CTO suction and ammonia levels are OK – have ammonia tote ready to change out at all times. 3 full totes are in the dept.

Exhaust to CTO – NOTE: CTO is in manual. Leave in manual at 38%.

#4 RC / Ni 2458:

Can begin running when able

Watch it closely as this is a high nox product.

NOTE: Auto sampler is now working.

Exhaust Trimer

#5 RC / 4010 done:

On hold for modifications.

NOTE: bags 15 and 16 are not to be fed – they are in the red zone in Bldg 31 and can be scrapped. Need to be repacked to Haz-waste bags. Maybe through the PK when 4010 is complete?

Exhaust to

#6 RC & Dryer / D-1781 next

We can start the calciner

We have a batch ready to go from the pfaudler.

MOD for D 1781 is in control room.

Exhaust to Sly Scrubber

6 Tank / Ni 2458 solution

Tank adjusted on afternoons. 4-1-15

New Pfaudler / Ni 2458:

Tank made on afternoons- sample is in the lab we are awaiting results.

Pump is working fine now and a screen was installed over the wand for the tote so hopefully we will not clog again. Use trays to catch solution under totes.

7 Tank Vanadyl Oxalate solution for V 2045 empty:

Tank was being acid washed several days ago...status?

Old Pfaudler / D-1781 next

1st batch made on afternoon shift. #6 needs to be finished asap so that we can start feeding material.

National Dryer: Ni 2458

Continue to feed as material available.

National is now working, High level probe on discharge was active due to material in hopper. This was kicking out the dryer when the belt was turned on.

PK Blender / AL-3915 Pill Mix:

PK is not able to be run due to DC lines being removed for installation of new DC equipment.

Outlet valve update: New Valve to be delivered soon...valve will have a spring that will keep it closed when there is no air to the valve.

Abbe Blender / 5206 Done

Done for a while. Area Cleaned.

Tower 3 Cu 0860:

Tower is running but still on high amps even with the change.

Tower 6 / QVAM:

Tower is running. Should be down on late on midnights

North Screener / Cu-0860:

Done...

South Screener / change over to E 474:

Done.

#2662 (west) Pill Machine / Al-3915:

Running, having flow issues

#2664 (east) Pill Machine / Al 3915:

Running, having flow issues

TK #2 / Be0101, transition to V 2045...

Continue loading and unloading. Make sure temps are OK.

There are only a few bags left to feed. We will need to switch #2 Kiln out for V-2045 next.

Bl-mill is being cleaned and needs to be ready to mill when kiln starts.

TK #4 / V 2045 next:

WOW for reprograming to turn off screener when drum is full

Mark would like a final count of the fines drums.

Harrop Kiln / AI 3921 finishing soon, AI 3920 next:

Continue...split the time on the kiln with the screener or other personnel (4 hrs). We are now loading the front half of the car and the top 2 saggars on the back half of the saggars. Operators will be switched out half way through the shift.

NOTE: work order written for improved lighting fixture over car rail unloading zone (just out of cooling zone).

Building 27 Belt Filter / Cu 5020:

Running- Continue

Tank 6 Pump repaired 3/31 afternoons.

Trying to determine if we can remove some of the totes of solution that are sitting on the 1st floor.

Priorities:

Priorities 1 through 9 are basically all the same priority, should be considered urgent and will require call outs for maint issues and/or processing issues.

- 1) #5 RC
- 2) #1 MED/RC
- 3) Reduction Towers
- 4) West Pfaudler/National Dryer/#4 RC
- 5) East Pfaudler/#2 T kiln
- 6) Harrop Kiln
- 7) Horne Tabletting Machines
- 8) #3 MED/cleaning
- 9) #2 Line/#2RC
- 10) Finish cleaning HC-11 Dryer & Calcine

WOWs, equipment issues, other issues:

F1 items – After all of the clean-up and repairs to various parts of F1, the suction is now very high but the reservoir tank continues to run over. Need to verify if OK to use. Currently have recirc pumps turned off.

Trimer items – Trimer is running again.

CTO – Running but DP on burner is high. Not yet out of range.